



# Marie Reed RC Lead in Water Test Results

## FY21 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 000946	6/4/2020	6/4/2021	1	Bottle Filler	In pool room 160	WF-06042020-000946	3/3/2021	FT-FY21-022021-000946-A	<1	FT-FY21-022021-000946-B	<1
WS- 000962	6/4/2020	6/4/2021	2	Bottle Filler	In gym room 280	WF-06042020-000962	3/3/2021	FT-FY21-022021-000962-A	<1	FT-FY21-022021-000962-B	<1
WS- 000966	6/4/2020	6/4/2021	2	Bottle Filler	In hallway across from phys ed office 272	WF-06042020-000966	3/3/2021	FT-FY21-022021-000966-A	<1	FT-FY21-022021-000966-B	<1